Project: AGOR 28	Contract No.: N00014- 12-C-0305	Shipyard: Dakota Creek Industries		
Prepared by:	Date:	Program Officer:		
Paul D. Bueren	8 May 2015	Robert (Tim) Schnoor		
Scripps Institution of		Office of Naval Research		
Oceanography (SIO)		875 Randolph St		
297 Rosecrans St.		ONR 321		
San Diego, CA 98106		Arlington, VA 22203-1995		
<b>Distribution Statement A</b> : A distribution unlimited.	pproved for public release;	Report No. A002.078		

#### 1. Meetings:

- i. Attended weekly conference call
- ii. Builders Trials on Armstrong
- 2. The following Shipyard Question Submittals were reviewed and commented on:

No questions this reporting period.

- 3. Logistics:
  - i. Continuing to work on initial outfitting lists for Sally Ride.
  - ii. Working on NS5 Hierarchy
- 4. Operator Concerns:
  - Tuff-Mass MLV and Acoustic Tiles The yard is continuing to install the Quad-zero MLV in various locations throughout Sally Ride. DCI is holding off on installing any new insulation in the machinery spaces where dampening tiles are still exposed. For this reporting period, DCI has removed 100% of the dampening tiles from the Bow Thruster Room. Exposed areas were sanded to fair in the glue residue and the affected areas were primed. Delta-db is currently being applied.

BT Room sans tile



BT Room with Delta-db



maintaining the data needed, and c including suggestions for reducing	lection of information is estimated to ompleting and reviewing the collect this burden, to Washington Headqu uld be aware that notwithstanding and DMB control number.	tion of information. Send comment larters Services, Directorate for Inf	s regarding this burden estimate ormation Operations and Reports	or any other aspect of the s, 1215 Jefferson Davis	nis collection of information, Highway, Suite 1204, Arlington	
1. REPORT DATE <b>08 MAY 2015</b>		2. REPORT TYPE		3. DATES COVE 00-00-2015	ERED 5 to 00-00-2015	
4. TITLE AND SUBTITLE				5a. CONTRACT	NUMBER	
AGOR 28				5b. GRANT NUMBER		
				5c. PROGRAM ELEMENT NUMBER		
6. AUTHOR(S)				5d. PROJECT NUMBER		
				5e. TASK NUMBER		
				5f. WORK UNIT NUMBER		
	ZATION NAME(S) AND AE of Oceanography (S	` '	s St.,,San	8. PERFORMING REPORT NUMB	G ORGANIZATION ER	
9. SPONSORING/MONITORING AGENCY NAME(S) AND ADDRESS(ES)				10. SPONSOR/MONITOR'S ACRONYM(S)		
				11. SPONSOR/M NUMBER(S)	ONITOR'S REPORT	
12. DISTRIBUTION/AVAII Approved for publ	ABILITY STATEMENT ic release; distribut	ion unlimited				
13. SUPPLEMENTARY NO	TES					
14. ABSTRACT						
15. SUBJECT TERMS						
16. SECURITY CLASSIFICATION OF:			17. LIMITATION OF ABSTRACT	18. NUMBER OF PAGES	19a. NAME OF RESPONSIBLE PERSON	
a. REPORT unclassified	b. ABSTRACT unclassified	c. THIS PAGE unclassified	Same as Report (SAR)	7	ALSI ONSIBLE I EKSON	

**Report Documentation Page** 

Form Approved OMB No. 0704-0188

#### DCI has started tile removal in the Stern Tunnel Room.

#### Tunnel Thruster Rm tile removal



Tunnel Thruster Rm Tile



The traction winch room has tiles on both side shells, the forward bulkhead and the overhead opposite the main working deck.

Traction Winch Rm fwd bulkhead tiles



Traction Winch Rm Overhead tiles.



- Sally Ride Quad-Zero MLV The yard continues to install the Quad-Zero in location with no sound dampening tiles. This includes the Main Engine Space overhead and aft bulkhead as well as the MCS. DCI has indicated that they will cover the foil backed Quad-zero MLV in the MCS with sheathing.
- Ship Service Diesel Generator Emergency Shutdowns This issue remains open and must be retested to prove that it works.
- Main Deck Noise Levels, Armstrong –The baffles are installed but with little reduction in noise levels as far as I could tell alongside the pier.

Side & CTD Handling Systems – Dockside testing of Armstrong's CAST6 winches and their associated handling devices revealed that when either Handling Device is deployed, the cable goes hard up against the retaining pin at the top of the outboard turning block. Issue is still open. Markey to be on site next week for more tuning.



- Main Deck Vent Closures Issue remains open.
- Load Shedding Awaiting verification that the necessary cables and shut trips have been installed.
- SSHD Controls Waiting to see how this issue is addressed by Markey/Systems Interface. A
  CTD LARS/SSHD Handling selector switch has not been installed in the Aft Control Station as
  yet.
- Main Crane Towing & Coring Crutch The crutch assembly being provided by Allied Systems needs to be demonstrated to prove that it can be used in a safe and practical way.
- Reach Rods DCI has agreed to install reach rods to the two 10-inch sea valves at the starboard sea chest. An additional reach rod may be required on the 6-inch deicing line and the emergency fire pump sea chest valves.

### 5. Sally Ride Progress:

- Load Bank Testing DCI is working towards the week of May 18 to begin load bank testing of the four SSDG's and the EDG. The necessary electrical and piping systems are being prepped towards this end.
- Fuel Service Piping Flushing has been completed and all piping and hoses have been reconnected.



- Diesel Oil Day Tanks port and starboard day tanks were cleaned and inspected prior to filling with fuel.
- Engine Exhaust Work continues on completing the exhaust system insulation. DCI may be a bit behind schedule with this work. It needs to be completed prior to any prolonged running of the engines.
- Diesel Engines Cummins Northwest has been aboard prepping the engines. Yard personnel are cleaning dust and debris from and around the engines.
- Central Fresh Water Piping Hydro testing was completed and flushing is to commence this
  evening and through the weekend. Pumps are aligned and wired for service

- Deck Machinery Hydraulic Piping Last runs are going into the aft bosun locker.
- Pilot House Fiddle boards are up and being populated with equipment. Hook-up to bridge equipment continues.

Chart Room Fiddle Board



Centerline Fiddle Board



• Outfitting – Bunks and fixtures are being installed in accommodation spaces.



# 6. Call-outs: Sally Ride:

- Diesel Oil Day Tanks final inspection for material condition and cleanliness. Both tanks were clean and read for fuel.
- Fresh Water Cooling Hydro Test System pressurize with water to 67-psi. Entire system inspected for leaks. No problems to report.
- DO Stripping System System pressurized with air. No leaks detected.

## 7. The following DRL's were reviewed and commented on:

1st App Hull No	DRL No	Document Title	Occur No/Rev No
AGOR27	A055	TM Report - COMMERCIAL TECHNICAL MANUALS AND SUPPLEMENTAL DATA (#551 DI-055 (TM) for 244 Craft Bearing Self-Aligning Split Roller Bearing)(R/ASR)	1097/0
AGOR27	A058	STD Report - INSTRUCTOR GUIDES (#08 DI-058 Instructor Guide for Bronswerk Marine (2 Drawings / 1 Guide / 1 Letter))(R/ASR)	18/0
AGOR27	A059	STD Report - STUDENT GUIDES (#17 DI-059 Student Guide for Bronswerk Scientific Refrigeration)(R/ASR)	31/0
AGOR27	A031- 03	STD Report - TEST PROCEDURES (331-001-3 Lighting Systems Interior & Labs Rev-)(R/ASR)	257/0
AGOR27	A031- 03	STD Report - TEST PROCEDURES (555-006-3 Fixed Fire Extinguishing Galley Hood Demo Rev-)(R/ASR)	259/0
AGOR27	A031- 03	STD Report - TEST PROCEDURES (516-001-3 Scientific Refrigeration Plants Test Rev-)(R/ASR)	261/0
AGOR27	A031- 04	STD Report - TEST REPORT (561-001-4 Steering Gear Controls System Test) (R/ASR)	154/0
AGOR27	A031- 04	STD Report - TEST REPORT (593-001-3 MSD System Operational Test) (R/ASR)	156/0
AGOR27	A058	STD Report - INSTRUCTOR GUIDES (#10 DI-058 Instructor Guide for Siemens IAS)(R/ASR)	20/0
AGOR27	A058	STD Report - INSTRUCTOR GUIDES (#11 DI-058 Instructor Guide for Siemens Integrated Electrical Plant)(R/ASR)	22/0
AGOR27	A059	STD Report - STUDENT GUIDES (#20 DI-059 Siemens Integrated Electrical Plant Student Guide)(R/ASR)	33/0
AGOR27	A059	STD Report - STUDENT GUIDES (#19 Siemens IAS Student Guide)(R/ASR)	35/0



